



5445 CORPORATE DRIVE  
TROY, MICHIGAN 48098  
(248) 641-1600

HARNES, DICKEY & PIERCE, P.L.C.  
ATTORNEYS AND COUNSELORS  
P.O. BOX 828  
BLOOMFIELD HILLS, MICHIGAN 48303  
U.S.A.

CABLE  
PATENTS TROY, MICHIGAN  
TELEX NO. & REPLY  
287637 HARNES UR  
TELEFACSIMILE  
(248) 641-0270

September 5, 2001

Hon. Commissioner of Patents and Trademarks  
Washington, D.C. 20231

Re: U.S. Patent No. 6,213,731 B1  
Issued April 10, 2001  
For: Compressor Pulse Width Modulation  
Roy J. Doepker et al, Inventor

Dear Sir:

We have noted, in proofreading the subject patent, the errors listed on the enclosed Certificate of Correction form. Our records indicate that these errors were made by our office. Enclosed is our check in the amount of \$100.00 to cover the cost thereof. The Commissioner is hereby authorized to charge any deficiency in the payment of this fee to Deposit Account No. 08-0750.

The corresponding location in the application of the errors in question is as follows:

The first error appears on page 3, line 25 of the application.

The second error appears on page 9, line 13 of the application.

The third error appears on page 12, line 26 of the application.

Please certify the enclosed Certificate of Correction and return same to

**CERTIFICATE**

SEP 14 2001

**OF CORRECTION**

**APPROVED**

MAR 9 2002

FOR THE DIRECTOR OF USPTO

Very truly yours,

By

Charles H. Blair  
Registration No. 19734  
(Attorney for Applicant)

09/17/2001 YPOLITE2 00000031 6213731

01 FC:145

100.00 OP

Page 2

CHB/d  
0315-000452

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,213,731 B1  
DATED : April 10, 2001  
INVENTOR(S) : Roy J. Doepker et al

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

✓ Column 2, line 43, after "**refrigeration**" insert -- **compressor** --. A

✓ Column 5, line 57, "**tubes**" should be -- **tube** --. A


✓ Column 7, line 60, "**tubes**" should be -- **tube** --. A

MAILING ADDRESS OF SENDER:

Charles H. Blair  
Harness, Dickey & Pierce, P.L.C.  
P.O. Box 828  
Bloomfield Hills, MI 48303

PATENT NO. 6,213,731 B1

No. of add'l copies  
@ 50¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,213,731 B1  
DATED : April 10, 2001  
INVENTOR(S) : Roy J. Doepker et al

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 43, after "refrigeration" insert -- compressor --.

Column 5, line 57, "tubes" should be -- tube --.

Column 7, line 60, "tubes" should be -- tube --.

MAILING ADDRESS OF SENDER:

Charles H. Blair  
Harness, Dickey & Pierce, P.L.C.  
P.O. Box 828  
Bloomfield Hills, MI 48303

PATENT NO. 6,213,731 B1

No. of add'l copies  
@ 50¢ per page

